

Kaybob Area Incident – June 2017 Update

Actions taken between June 1, 2017 and June 30, 2017 to remediate the spill included:

- Sampling and Monitoring:
 - Continued water sampling activities and field screening from selected areas
- Water Management Activities:
 - Continued to pump recovered water into 2-9 injection facility
 - Continued diverting fresh water around release area
 - Discharged fresh water from spill area following field testing
- Wildlife Monitoring:
 - Continued daily monitoring for wildlife sightings
 - Checked and maintained wildlife deterrents
- Water Control and Containment:
 - Inspected aqua dams to ensure effectiveness. All aqua dams are operational
 - Conducted ongoing inspection and maintenance of existing booms
 - Conducted ongoing inspection and maintenance of terrestrial barriers
- Other:
 - We are working closely with the Alberta Energy Regulator and are in ongoing communication with them. We will continue to do so throughout the remediation of the site

Subject to weather conditions, actions planned commencing July 1, 2017 include:

- Continue analytical updates from delineation and monitoring points (water samples)
- Monitor and maintain trenches
- Conduct water sampling and field screening from selected areas
- Continue to inspect and maintain the booms
- Continue to monitor for wildlife activity and maintain wildlife deterrents
- Continue recovering water into on-site storage tanks for injection into 2-9 disposal facility
- Continue diverting fresh water around the release area
- Continue discharging fresh water from spill area following field testing as required