

Kaybob Area Incident Update: January 6, 2017

Actions taken between December 23, 2016 and January 5, 2017 to remediate the spill included:

- Sampling and Monitoring:
 - Continued water sampling activities and field screening from selected areas
 - Monitoring wells have now been installed and will be tested on an ongoing basis
- Recovery and Waste Management:
 - Due to frozen site conditions, no fluids were recovered from trenches
 - Conducted ongoing inspection and maintenance of existing booms
 - Continued with remediation of the release area
- Wildlife Monitoring:
 - Continued daily monitoring for wildlife sightings
 - Checked and maintained wildlife deterrents
- Water Control and Containment:
 - Inspected aqua dams to ensure effectiveness. All aqua dams are operational
 - Inspected and maintained all booms
- Other:
 - We are working closely with the Alberta Energy Regulator and are in ongoing communication with them. We will continue to do so as we proceed with our investigation of the incident and as we conduct a thorough clean-up and remediation of the site

Subject to weather conditions, actions planned for the week beginning January 6, 2017 include:

- Continue analytical updates from delineation and monitoring points (water samples)
- Monitor and maintain trenches, recover fluids (if any) and haul to disposal site
- Conduct water sampling and field screening from selected areas
- Inspect and maintain the booms
- Continue to monitor for wildlife activity and maintain wildlife deterrents
- Continue with remediation of the release area