

## **Kaybob Area Incident Update: October 20, 2016**

Actions taken October 19<sup>th</sup>, 2016 included:

Continued focus on improving site access, water control, recovering fluids and collecting water and soil samples.

- Access:
  - Continued to grade and maintain primary access road to minimize damage to the road and minimize driving safety hazard
  - Continued improving access to release point
  - Continued inspections of the site
- Sampling:
  - Continued water sampling activities
- Recovery, Containment and Waste Management:
  - Fluid continues to be recovered and pumped into onsite tanks, then transported for disposal at an approved waste facility
  - Completed lining of soil containment cell
  - Inspected and maintained existing booms
- Wildlife Monitoring:
  - Wildlife crew continued to monitor for wildlife
  - Completed sweeps at spill perimeter for wildlife signs and game trails
  - Measured and monitored level of water at selected locations
  - Continued to maintain and improve fencing and bird deterrents
- Water Control:
  - Maintained and extended aqua dam. Aqua dam is operational and is diverting freshwater from the release area
- Other:
  - Trilogy continues to work to determine the cause of the leak and the volume of the spill

Subject to weather conditions, actions planned for October 20<sup>th</sup> include:

- Continue analytical updates from delineation and monitoring points (water and soil samples)
- Monitor and maintain both trenches and dispose of fluids recovered from trenches
- Conduct soil and water sampling and field screening from selected areas
- Inspect and maintain the booms
- Continue to recover fluids and haul to disposal site
- Continue to monitor saturation levels above the suspected release point location to improve access to release point
- Continue inspections and surveillance, monitor and divert wildlife, maintain and improve fencing and bird deterrents. Continue water measurement and monitoring activities